



Release Notes for Drivers Pack 3.1.10

Drivers Pack 3.1.10 recommended to use with the base products Axxon Intellect Enterprise v.4.8.0 or Axxon Smart PRO v.2.0.1

New integrations of IP-devices

- Basler BIP2-1300c
- Basler BIP2-1300c-dn
- Bosch NBN-498-12P
- Brickcom FD-130-Ap
- Brickcom WCB-100-Ap
- Brickcom WFB-100-Ap
- CNB IDC 4050IR
- CNB IDC 4050F
- CNB IDP 4000VD
- CNB IGP 1030
- CNB IVC 4000T
- CNB IVP 4030VR
- Etrovision EV3151A
- Etrovision EV8150A
- FineCCTV CDV-3V930HU
- FlexWatch FW-1173-DS
- FlexWatch FW-1178-PE
- FlexWatch FW-3470
- FlexWatch FW-5870C
- IQeye IQ040S
- IQeye IQ041S
- IQeye IQ510
- IQeye IQ541S
- IQeye IQ702
- IQeye IQ703
- IQeye IQ705
- IQeye IQ732N
- IQeye IQ751
- IQeye IQ752
- IQeye IQ753
- IQeye IQ755
- IQeye IQ851
- IQeye IQ852
- IQeye IQ853
- IQeye IQ855
- IQeye IQA20S
- IQeye IQA22S
- IQeye IQA23S
- IQeye IQA25S
- IQeye IQD40S
- IQeye IQD42S

- Panasonic WV-NP502E
- Panasonic WV-NW502S
- Panasonic WV-SP306E
- Samsung Techwin SNB-1000P
- Samsung Techwin SNB-3000P
- Samsung Techwin SND-1010P
- Samsung Techwin SNV-3080P
- Samsung Techwin SNV-3120P
- Samsung Techwin SPE-100P
- Sony SNC-CH140
- Sony SNC-CH240
- Sony SNC-DH120T
- Sony SNC-DH140
- Sony SNC-DH240
- Sony SNC-RH124
- Sony SNC-RS46N
- Sony SNC-RS46P

Installation

For updating installation start file **IPDriverPack.msi**.

Installation of updating requires previously established base software.

It is not require restarting base software.

More details about supported functions in each IP-device look on a site of the manufacturer at the list of supported IP devices for version of the base product.

www.itv.ru

www.axxonsoft.com